Weathertzenton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR-0154/1

Work Order Type: Weatherization

Audit Name: 20002BR-0154-Audit

CLIENT INFORMATION

Client Name: 20002BR-0154 Address:

Client ID: 20002BR-0154

Alt. Client ID: Bradley County

CLIENT CONTACT INFORMATION

20002BR-0154 Applicant/Person of Record

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency Agency Phone: (423) 479-4111

Address: 155 Sixth Street SE **Fax:** (423) 479-4113

Cleveland, TN 37320 *Email Address:* jswestfield@hotmail.com

Agency Contact: Birger, Perry Work Phone:

Cell Phone: (615) 566-4085

Email Address: birgerwood@aol.com

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Site Built Home Build date est 1998

Client Name: 20002BR-0154
Client ID: 20002BR-0154
Alt. Client ID: Bradley County

Work Order (Bid Form)

Work Order Name: WO/20002BR-0154/1 Report Run On: 5/20/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 3

Measures

Measure 1 DW	/H Tank Insulation			Componen	ts		ı	Inspected		
Comment										
				Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
Hot Water Equipment	DHW Tank Insulation	Each	1							
2 Labor	DHW Tank Insulation	Each	1							
Other Detail										
		Measure Sub Total:				Sub Total:				
Field Notes:										
Measure 2 DW Comment 10'	/H Pipe Insulation			Componen				Inspected		
Comment 10'		Units		Estimated	<u>'</u>	Otv	Actual			
	/H Pipe Insulation Description / Comment DHW Pipe Insulation cost for 10' of wrap	<i>Units</i> Each	Qty 1	-		Qty		Inspected Total		
Comment 10' # Material / Labor	Description / Comment DHW Pipe Insulation		Qty	Estimated	<u>'</u>	Qty	Actual			
Comment 10'# Material / Labor1 Insulation	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	Qty 1	Estimated	<u>'</u>	Qty	Actual			
Comment 10'# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	Qty 1	Estimated	<u>'</u>	Qty	Actual			
Comment 10'# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	Qty 1	Estimated	<u>'</u>	Qty	Actual			
Comment 10'# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	Qty 1 1	Estimated	<u>'</u>		Actual			
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	Qty 1 1	Estimated Unit Cost	<u>'</u>		Actual Unit Cost			
Comment 10'# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	Qty 1 1	Estimated Unit Cost	<u>'</u>		Actual Unit Cost			
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	Qty 1 1	Estimated Unit Cost	<u>'</u>		Actual Unit Cost			

Measure 3 Floor Ins. R-19			Components Crawlspace					Inspected	
Comment No insul	ation existing in crawlspa	ace.							
			Estimated				Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1600						
Other Detail									
			Measure	Sub Total:			Sub Total:		
Field Notes:									
Measure 4 Pres	sureRelief Piping Need	led		Componen	ts Water	Heate	r	Inspected	
Comment located i				Componen	VVG(C)	ricato		$\dot{\Box}$	
Comment located	in garage		Estimated				Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Health and Safety Items	Pressure relief piping	Each	1						
2 Labor	Labor	Hour	1						
04 5 4 4							<u> </u>		
Other Detail									
]						
			Measure	Sub Total:			Sub Total:		
Field Notes:									
		Work O	rdor Gra	nd Total		Gran	d Total		

Report Run On: 5/20/2010